

# HEV Fleet Testing - Maintenance Sheet

## 2002 – Toyota Prius Hybrid



U.S. Department of Energy  
Energy Efficiency  
and Renewable Energy



## Advanced Vehicle Testing Activity

VIN #JT2BK12U920038976

Date	Mileage	Description	Cost
3/22/2002	7,607	Change oil and rotate tires	\$ 27.00
5/9/2002	15,309	Change oil and rotate tires	\$ 27.00
6/25/2002	22,523	Change oil and rotate tires	\$ 27.00
7/8/2002	24,057	Replace two tires	\$ 127.32
7/29/2002	27,950	Change oil and rotate tires	\$ 27.62
8/21/2002	31,897	Check Engine Light illuminated. Dealer found a broken wire due to manufacturer defect in wire harness of vacuum sensor	warranty
9/3/2002	33,432	Change oil and rotate tires	\$ 29.00
9/30/2002	38,777	Change oil and tire rotation	\$ 29.00
10/17/2002	40,769	Rear wheel hub and bearing replaced	\$ 321.26
11/7/2002	44,726	Check Engine Light illuminated. Dealer found a broken wire due to manufacturer defect in wire harness of vacuum sensor	warranty
11/1/2002	43,592	Change oil and rotate tires	\$ 29.11
12/16/2002	51,087	Change oil and rotate tires	\$ 30.99
3/17/2003	66,958	Change oil and rotate tires	\$ 30.34
4/25/2003	74,980	Change oil and rotate tires	\$ 30.67
5/28/2003	80,088	Change oil and rotate tires	\$ 30.50
7/7/2003	85,321	Change oil and rotate tires	\$ 30.31
7/15/2003	86,263	Numerous trouble lights illuminate on dash. Dealer reset trouble codes. No other repairs required	\$ 85.00
8/19/2003	90,775	90,000 mile service	\$ 392.52
8/5/2003	88,466	Change one tire	\$ 63.19
11/4/2003	103,228	Change oil and rotate tires	\$ 24.71
12/9/2003	108,429	Change oil and rotate tires	\$ 26.23
1/30/2004	115,895	30,000 mile service	\$ 390.30
3/26/2004	122,889	Repair accident damage	----
3/30/2004	123,403	Change oil and rotate tires	\$ 27.00
4/29/2004	127,430	Engine running erratically. Engine Control Module replaced.	\$ 1,217.70
5/6/2004	128,152	Change oil and rotate tires	\$ 28.15